



#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:		)	) Evaminary Christina Syma	
SATOSHI OKADA, ET AL.		<ul><li>Examiner: Christine Sung</li><li>Group Art Unit: 2878</li></ul>		
Appl. No.: 10/066,618			Group Art Unit: 2878	
Filed: February 6, 2002		; )		
For:	SCINTILLATOR PANEL, RADIATION DETECTOR AND MANUFACTURE METHODS THEREOF	; ; ; ;	Certificate  DEC 2 1 2005  of Correction	
U.S. Patent No.: 6,847,041 B2		)		
Issued: January 25, 2005		)	December 15, 2005	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

### CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

12/19/2005 JADDO1 60000112 6847041

Accompanying this letter is a check for \$100.00 to cover the statutory 100.00 OP fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA\_MAIN 96137v1

# Staple Here Gulyl MINER'S TRIM LINE

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,847,041B2

DATED

January 25, 2005

INVENTOR(S) :

SATOSHI OKADA, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 17:

Line 52, "cite" should read --site--; and Line 55, "cite" should read --site--.

#### COLUMN 18:

Line 25, "50 μum" should read --50 μm--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

CA\_MAIN 96153v1

PATENT NO. 6,847,041

No. of add'l. copies @ 30¢ per page

=>

#### UNITED STATES PATENT AND TRADEMARK OFFICE

#### **CERTIFICATE OF CORRECTION**

PATENT NO.

6,847,041 62

**DATED** 

January 25, 2005

INVENTOR(S) :

SATOSHI OKADA, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 17:

Line 52, "cite" should read --site--; and Line 55, "cite" should read --site--.

#### COLUMN 18:

Line 25, "50 μum" should read --50 μm--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

CA\_MAIN 96153v1

PATENT NO. 6,847,041

No. of add'l. copies @ 30¢ per page

ightharpoonup